

WORK ORDER

(EXTRA WORK ORDER)

DELIVERY DUE DATE:

661

Procurement Unit Telefax No.: 045-982-4630

Supplier: REDVOLKS ENTERPRISE

Address: #66 Mac Arthur Highway, Sitio Valdez, San Rafael, Tarlac City

TIN .

211-781-005-000 Non-VAT

0909-112-6066 Tel. No.:

Work Order No.: 2019-065

Date:

4/24/2019

10 No.:

2019-026

Date:

1/24/2019

Mode of Procurement: Small Value

Mode of Payment:

n/30

SIR/MADAM:

You are hereby advised to accomplish/deliver the following job/work on within 21 days as per

recommendation of the TSU Infrastructure Management Office duly approved by the President of the Agency. TOTAL COST **UNIT COST** DESCRIPTION UNIT OTY. LABOR AND MATERIALS: REPAIR OF TSU lot 1

SWIMMING POOL AT LUCINDA CAMPUS (21 DAYS / 3 WEEKS) 1 Year warranty Bill Of Quantities: 1.0 General Requirements 10,000.00 10,000.00 1.1 Mobilization/ Demobilization 226,350.00 226,350.00 2.0 Materials 55,000.00 55,000.00 3.0 Labor 291,350.00 Total Labor & Materials cost: 20,394.50 7% VAT: 311,744.50 TOTAL PROJECT COST:

(Please read carefully at the back hereof)

CONFORME	& RECEIVE	COPY:
----------	-----------	-------

Bank Account Name:

Bank Account Number: __

Bank Name: _ Bank Address: __

COMMISSION ON AUDIT- TSU

FUNDS AVAILABLE:

IESUS S. DANGANAN

Budget Officer IV

APPROVED:

DR. GLENARD T. MADRIAGA

VP, Admin. & Finance

Authorized Official

Form No.: TSU-PRO-SF-10

Revision No.: 01

Effectivity Date: March 01, 2017

Page 1 of 1