

WORK ORDER

DELIVERY DUE DATE

Procurement Unit

Tel. No.: (045) 606-8142

TOYOTA SAN FERNANDO PAMPANGA, INC. Supplier:

Work Order No.: 2023-018

Address:

Olongapo-Gapan Road, City of San Fernando 2000, Pampanga

1/26/2023

TIN:

234-410-504-002 VAT Reg.

2023-021

Tel. No.:

(045)961-1188/(045)961-8011

IO No.: Date: 1/18/2023

Mode of Procurement: Direct Contracting

Date:

Mode of Payment:

N/15

SIR/MADAM:

You are hereby advised to accomplish/deliver the following job/work upon receipt of the Work Order as per quotation submitted by you duly approved by the TSU Committee on Bids and Awards and the President of the Agency

TY. UNIT DESCRIPTION	UNIT COST	TOTAL COST
lot REPAIR AND MAINTENANCE FOR COASTER PO 584, Brake Pads 3.5MM Need to Replace Brake Pads Next Service need to Replace Rear Oil Seal & Gasket Damage	L- 34,619.71	34,619.71

(Please read carefully at the back hereof)

Charge to:	02.201441
ROA No.:	2023-02-0287
CONFORM	E & RECEIVE COPY:
	1 10

JASPER A. YAUDER, CPA

Budget Officer

Firm/Dealer/Supplier/Contractor

3/13/23

Bank Account Name:

Bank Account Number:

Bank Name:

Bank Address:

APPROVED:

DR. GRACE N. ROSETE

Vice President for Administration

Authorized Official

Form No.: TSU-PRO-SF 10 Revision No.: 01

Effectivity Date: March 1, 2017

Page 1 of 1