

WORK ORDER

DELIVERY DUE DATE /1-28-19

Procurement Unit Telefax No.: 045-982-4630

Supplier:

MOLAVE TRADING INC.

Address:

891 E. Delos Santos Ave., Quezon City

000-390-460-000

Tel. No.:

(02) 411-0360 to 64

Work Order No.:

2019-103

Date:

7/23/2019

10 No.:

Mode of Procurement: Small Value

4/24/2019

Mode of Payment: 30

SIR/MADAM:

You are hereby advised to accomplish/deliver the following job/work upon receipt of the Work Order upon receipt of as per quotation submitted by you duly approved by the TSU Committee on Bids and Awards and the

QTY.	UNIT	DESCRIPTION	UNIT COST	TOTAL COST
1		CHECK-UP, REPAIR OF FILTER ASSEMBLY OF AGILENT CARY-60 UV-VIS SPECTROPHOTOMETER	17,920.00	
	104	Labor: (1 SERVICE CHECK-UP OF AGILENT CARY 60 UV-VIS SPECTROPHOTOMETER) ON-SITE (1 SERVICE REPAIR AGILENT CARY 60 UV-VIS	17,720.00	
		SPECTROPHOTOMETER) ON-SITE (1UNIT REPLACEMENT OF FILTER ASSEMBLY) ON-SITE	,	
		Materials: Assy Filters (Item No.110628190)	24,259.28	
	1	3MONTHS WARRANTY FOR THE SERVICE		42,179.

(Please read carefully at the back hereof)

EMMANUEL A. ACERO

MOLAVE TRADING INC.

Firm/Dealer/Supplier/Contractor AUGUST 30, 20

Bank Account Name:

Bank Account Number: Bank Name:

Bank Address: _

JESUS S. DANGANAN Budget Off er IV

FUNDS AVAILABLE:

APPROVED:

DR. GLENARD T. MADRIAGA

P, Admin. & Finance Authorized Official V.

RECEIVED COPY:

DATE JO/PR RECEIVED:

Form No.: TSU-PRO-SF 10 Revision No.: 01

Effectivity Date: March 1, 2017

Page 1 of 1

WORK ORDER

DELIVERY DUE DATE 11-28-19

Procurement Unit Telefax No.: 045-982-4630

Supplier:

MOLAVE TRADING INC.

Address:

891 E. Delos Santos Ave., Quezon City

TIN: Tel. No.: 000-390-460-000

(02) 411-0360 to 64

Work Order No.: 2019-103

Date:

7/23/2019

JO No.:

2019-085

Date:

4/24/2019

Mode of Procurement: Small Value Mode of Payment: 30

SIR/MADAM:

You are hereby advised to accomplish/deliver the following job/work upon recent of the Work Order upon receipt of as per quotation submitted by you duly approved by the TSU Committee on Bids and Awards and the

QTY.	UNIT	DESCRIPTION	UNIT COST	TOTAL COST
1		CHECK-UP, REPAIR OF FILTER ASSEMBLY OF AGILENT CARY-60 UV-VIS SPECTROPHOTOMETER		
		Labor: (1 SERVICE CHECK-UP OF AGILENT CARY 60 UV-VIS SPECTROPHOTOMETER) ON-SITE (1 SERVICE REPAIR AGILENT CARY 60 UV-VIS SPECTROPHOTOMETER) ON-SITE (1UNIT REPLACEMENT OF FILTER ASSEMBLY) ON-SITE	17,920.00	
		Materials: Assy Filters (Item No.110628190)	24,259.28	42,179.
		3MONTHS WARRANTY FOR THE SERVICE		

(Please read carefully at the back hereof)

MOLAVE TRADING INC. Firm/Dealer/Supplier/Contractor	1 3 SEP 2019	JESUS S. DANGANAN Budget Officer IV		
Date Bank Account Name:		APPROVED:		
Bank Account Number:Bank Name:		DR. GLENARD T.	MADRIAGA	
Bank Address:		VP, Admin. & Authorized	Finance	
RECEIVED COPY: DATE JO/PR RECEIVED:			D 1 - 6.1	
Form No.: TSU-PRO-SF 10 Revision No.: 01	· (8) KEE	Effectivity Date: March 1, 2017	Page 1 of 1	