WORK ORDER

DELIVERY DUE DATE:

8 6 21

Procurement Unit

Tel No.: 045-606-8142/ 696-8157

Supplier:

REDVOLKS ENTERPRISE

Address:

Blk. 8 Lot 49. Tuscany Subd., Burot, Tarlac City

TIN:

211-781-005-000 Non-VAT

Tel. No.:

0909-112-6066

Work Order No.: 2021-071

Date: JO No.: 6/30/2021 2021-069

5/27/2021

Date:

Mode of Procurement:

Small Value

Mode of Payment:

n/30

SIR/MADAM:

You are hereby advised to accomplish/deliver the following Job/work within Thirty (30) Calendar days upon receipt of the Work Order as per quotation submitted by you duly approved by the TSU Committee on Bids and Awards and the

QTY.	UNIT	DESCRIPTION	UNIT COST	TOTAL COST
		REPAIR/REPLACEMENT OF PARTS IN THE WATER SYSTEMS		
		-Bladder Tank- Membrane mb 1000-1500 (Part no. 4481)	42,400.00	42,400.00
1	lot	-Bladder tank- S. Seal HQPO 20170424- 1 1/4" (Part no. 13607)	3,500.00	3,500.00
		-Bladder Tank- SVC Change bladder and shaft seal (part no. 123549)	9,500.00	9,500.00
		-Bladder labor cost	25,000.00	25,000.00
		-12% Gov't VAT	9,648.00	9,648.00
		-10% Overhead Contingency Misc. (OCM)	8,040.00	8,040.00
		**********************		98,088.00
				8
			COMMISSION ON AUDIT TSU;	
			v. 61 - 0 - 0 - 8	10 to e: 2021

(Please read carefully at the back hereof

Charge to: 11444] 1911-17-1918 ROA No. 1 RECEIVE COPY:

PAMOS SENTERPRISE intractor VL 202

2AMIL Bank Account Name: _ 75 905 Bank Account Number

RCBC Bank Name:

LUISITA Bank Address:

FUNDS AVAILABLE:

RYAN R. RØNQUILLO

OIC, Budget Office

APPROVED:

DR. ARMEE N. ROSEL

VP, Research & Extension Servi

Authorized Official

Effectivity Date: March 01, 2017

Page 1

Form No.: TSU-PRO-SF 10

Revision No.: 01

WORK ORDER

DELIVERY DUE DATE:

Tel No.: 045-606-8142/606-8157

Supplier:

REDVOLKS ENTERPRISE

Address:

Blk. 8 Lot 49, Tuscany Subd., Burot, Tarlac City

TIN:

211-781-005-000 Non-VAT

Tel. No.:

0909-112-6066

Work Order No.: 2021-071

Date:

6/30/2021

JO No.:

2021-069

Date:

5/27/2021

Page 1 of 1

Effectivity Date: March 01, 2017

Mode of Procurement:

Small Value

Mode of Payment:

<u>n/30</u>

SIR/MADAM:

You are hereby advised to accomplish/deliver the following job/work within Thirty (30) Calendar days upon receipt of the Work Order as per quotation submitted by you duly approved by the TSU Committee on Bids and Awards and the

QTY.	UNIT	DESCRIPTION	UNIT COST	TOTAL COST
		REPAIR/REPLACEMENT OF PARTS IN THE WATER SYSTEMS		
		-Bladder Tank- Membrane mb 1000-1500 (Part no. 4481)	42,400.00	42,400.00
1	lot	-Bladder tank- S. Seal HQPO 20170424- 1 1/4" (Part no. 13607)	3,500.00	3,500.00
1		-Bladder Tank- SVC Change bladder and shaft seal (part no. 123549)	9,500.00	9,500.00
		-Bladder labor cost	25,000.00	25,000.00
		-12% Gov't VAT	9,648.00	9,648.00
		-10% Overhead Contingency Misc. (OCM)	8,040.00	8,040.00
		**********************		98,088.00
		1		*
			RECE!	VED 2021
			Sy: Quy_Date: 0	THE SOL

Charge to: 100441 ROA No.: 101-07-0908 CONFORME & RECEIVE COPY:	(Please read carefully at the back hereof) 🧸	FUNDS AVAILABLE:
REDVOLKS ENTERPRISE Firm/Dealer/Supplier/Contractor		RYAN R. RONQUILLO OIC, Budget Office
Date		APPROVED:
Bank Account Name:		APPROVED:
Bank Account Number:		DR. ARMEE N. ROSEL
Bank Name:		
Bank Address:		VP, Research & Extension Service
		Authorized Official

Revision No.: 01

Form No.: TSU-PRO-SF 10